

TALBOTT SPRINGS ELEMENTARY SCHOOL

9550 Basket Ring Road • Columbia, MD 21045 • 410-313-6915 • (F) 410-313-6921 • tses.hcpss.org

November 8, 2019

Talbott Springs Families,

I am writing to inform you that the HCPSS Office of the Environment conducted an inspection and confirmed limited mold growth in rooms 54, 56, 57 and 60 (3rd grade classrooms).

Limited mold growth was identified on the interior doors of select cabinets in that pod area. The affected items were cleaned. Mold growth was not observed on any other types of surfaces in the area.

Moving forward, and as a precaution, all areas with the affected cabinet surface in the entire school building will be cleaned by a contractor after school hours on Friday, November 8, 2019 and Monday, November 11, 2019 and on Saturday, November 9, 2019. The HCPSS Office of the Environment will continue to monitor the school during the cooling season next summer.

As part of the IEQ process, information about Indoor Environmental Quality is posted on our school website at <https://tses.hcpss.org/environment>. Details about the HCPSS IEQ program is provided at ieq.hcpss.org.

Please feel free to contact me at nancy_thompson@hcpss.org with any questions.

Sincerely,

Nancy Thompson
Nancy Thompson
Principal